

FIG. 1




FIG. 2




FIG. 3




FIG. 4: SUCCESSFUL IS-95 TO IS-95 HARD HANDOFF




FIG. 5: SUCCESSFUL IS-95 TO ANSI/EIA/TIA.553 HARD HANDOFF




FIG. 6




FIG. 7




FIG. 8




FIG.




FIG. 10




FIG. 1




FIG. 1.




FIG. 1




FIG. 1.